

## Firmware Release Notes

Date: 4<sup>th</sup> April, 2019

Version: 3.8.9

Apply to: T300 Plus GNSS Receiver; T300 GNSS Receiver with SN T330XXXX

### New Features:

Support Galileo RTK

Improved the RTK, RTD performance (Need Base support Galileo corrections, T300 Base setup please choose RTCM32 MSM4)

Enlarge the buffer for 4G, solved the previous problem of large amount stations when connect CORS

Now the BT port will not stopped data flow after disconnect BT with controller

Fixed the bug of abnormal BT name